

TYPE OF MALFUNCTION:

- 1 HIGH WATER LEVEL IN TANK
- 2 WET AREAS NEAR SYSTEM OR SITE
- 3 NOTICEABLE ODORS
- 4 SEWER BACKUP INTO HOUSE
- 5 ABUNDANT GRASS GROWTH NEAR SYSTEM OR SITE
- 6 BACKFLUSH OF WATER FROM ABSORPTION AREA TO TANK
- 7 ANY OTHER INDICATION OF SYSTEM MALFUNCTION EXPLANATION

PIN	Street Address	Type of malfunction	Type of system	Investigated by SEO
40-37--2545-022	34 Appalachian Trail Road, Gardners	1,2,7	inground	Y
40-37-2545-010	29 Appalachian Trail Road, Gardners	2,3	inground	Y
40-15-0201-028	965 Baltimore Pike, Gardners	1,2,5	inground	Y
40-40-2652-011	205 Frost Road, Gardners	2,5 Permit #W00345?	ESM	Y
40-28-2098-010	7 Hamilton Rod, Boiling Springs	2, 5	inground	Y
40-24-0752-015	1417 Holly Pike, Carlisle 17013	5	inground	Y
40-12-0344-128	21 Joseph Drive	2	ESM	Y
40-39-2211-022	8 Logan Drive	2, 5	inground	Y
40-09-0535-001S	531 S. Middlesex Road	1,2,5	ESM	Y
40-09-0535-001T	533 S. Middlesex Road	2, 7-effluent surface on mound	ESM	Y
40-11-0288-065	2 Morrison Way	2	ESM	Y
40-13-0126-003	330 Motter Lane	2	inground	Y
40-11-0284-039	395 Mountain Road	1,5	inground	Y
40-12-0344-082	484 Mountain Road	2	ESM	Y
40-13-0126-023	614 Mountain Road	2	ESM	Y
40-14-0142-011	55 Oxford Road	1,2	inground	Y
40-11-0286-090	919 Petersburg Road	1,2,5	inground	Y
40-25-0060-009	414 Petersburg Road	1,2	inground	Y
40-11-0288-083	392 Pheasant Lane	2	ESM	Y
40-30-2642-028	414 Pine Road	2	inground	Y
40-26-0220-001	830 Ridge Road	2,7-poss. Broken pipe in mound	ESM	Y
40-10-0632-008	1503 Rockledge Drive	1,2,5	inground	Y
40-40-2656-025	25 Smith Road	1,2,7-pump not working, alarm not working	ESM	Y
40-09-0535-003	1535 W. Trindle Road	2, 7-stand pipes broke - fixed	ESM	Y
40-40-2654-035	80 Victory Church Road	1, 2, 5, 7-water leak from house	inground	Y
40-40-2656-006A	29 Victory Church Road	5	inground	Y
40-10-0632-011	510 Adams Road, Carlisle 17013	1	ESM	
40-37-2545-024	24 Appalachian Trail Road, Gardners	1	inground	
40-37-2545-006	9 Appalachian Trail Road, Gardners	1	inground	

TYPE OF MALFUNCTION:

- 1 HIGH WATER LEVEL IN TANK
- 2 WET AREAS NEAR SYSTEM OR SITE
- 3 NOTICEABLE ODORS
- 4 SEWER BACKUP INTO HOUSE
- 5 ABUNDANT GRASS GROWTH NEAR SYSTEM OR SITE
- 6 BACKFLUSH OF WATER FROM ABSORPTION AREA TO TANK
- 7 ANY OTHER INDICATION OF SYSTEM MALFUNCTION EXPLANATION

PIN	Street Address	Type of malfunction	Type of system	Investigated by SEO
40-37-2545-023	38 Appalachian Trail Road, Gardners	1,6	inground	
40-11-0286-057	404 Autumn Drive, Carlisle 17013	1	inground	
40-14-0142-026A	777 Baltimore Pike, Gardners	6	inground	
40-39-2209-006	802 Baltimore Pike, Gardners	1	inground	
40-38-2180-003	736 Baltimore Pike, Gardners	1	inground	
40-12-0342-042	140 Dedar Street, Mt. Holly Springs	1	inground	
40-22-0119-018	36 Fairview Street, Carlisle 17015	1,7	drywell	
40-11-0284-012A	360 W. First Street, Boiling Springs	1	inground	
40-16-0208-001A	58 Frost Road, Gardners	1	inground	
40-42-3277-007	101 Frost Road, Gardners	1	inground	
40-40-2652-007	187 Frost Road, Gardners	1, 6	inground	
40-43-2759-021	886 Goodyear Road, Gardners	1	ESM	
40-16-0208-010	900 Goodyear Road, Gardners	1	inground	
40-43-2759-029	903 Goodyear Road, Gardners	1	inground	
40-24-0746-057	190 Greenview Drive, Carlisle 17013	1	inground	
40-12-0346-007	617 Gutshall Road, Boiling Springs	4	ESM	
40-12-0344-008B	639 Gutshall Road, Boiling Springs	1	inground	
40-23-0585-006	7 Hilltop Circle, Carlisle	1	ESM	
40-23-0585-010	102 Hollenbaugh Road, Carlisle 17013	1	inground	
40-10-0632-005B	1532 Holly Pike, Carlisle 17013	1	inground	
40-23-0600-007	1230 Holly Pike	1	inground	
40-24-0752-010	1418 Holly Pike	1	inground	
40-10-0634-008	1445 Holly Pike	1, water leak into system?	inground	
40-22-0489-165	307 James Road	1	inground	
40-12-0344-129	23 Joseph Drive	1	ESM	
40-12-0344-133	26 Joseph Drive	1	ESM	
40-11-0288-003B	83 Ladnor Lane	1	inground	
40-11-0284-019A	1636 Leidigh Drive	1, 6	inground	
40-11-0286-005A	509 Lerew Road	1	inground	

TYPE OF MALFUNCTION:

- 1 HIGH WATER LEVEL IN TANK
- 2 WET AREAS NEAR SYSTEM OR SITE
- 3 NOTICEABLE ODORS
- 4 SEWER BACKUP INTO HOUSE
- 5 ABUNDANT GRASS GROWTH NEAR SYSTEM OR SITE
- 6 BACKFLUSH OF WATER FROM ABSORPTION AREA TO TANK
- 7 ANY OTHER INDICATION OF SYSTEM MALFUNCTION EXPLANATION

PIN	Street Address	Type of malfunction	Type of system	Investigated by SEO
40-11-0286-051	661 Lerew Road	1	inground	
40-11-0286-009	533 Lerew Road	1	inground	
40-10-0636-438	625 Lindsey Road	1	ESM	
40-09-0535-007	823 Lisburn Road	1	inground	
40-42-3277-004A	559 Meals Road	1	inground	
40-10-0638-021A	671 S. Middlesex Road	1,6	inground	
40-10-0638-021Q	691 S. Middlesex Road	1, 7-water leak from house	inground	
40-31-2187-050	113 Mill Street	1	inground	
40-12-0342-035TR03251	100 Motter Lane	1	inground	
40-12-0344-080	480 Mountain Road	1,6	inground	
40-12-0344-048A	525 Mountain Road	1	ESM	
40-13-0126-039A	615 Mountain Road	4	ESM	
40-12-0344-015	532 Mountain Road	1,6	inground	
40-14-0144-001	431 Old State Road	7-tanks leak water in	inground	
40-14-0142-047	200 Old Town Road	1	inground	
40-14-0142-039	46 Old Town Road	6	inground	
40-11-0288-003J	144 E. Old York Road	6	inground	
40-11-0288-012	160 E. Old York Road	5	ESM	
40-11-0288-086	141 E. Old York Road	1	ESM	
40-11-0288-003F	122 E. Old York Road	1,6	inground	
40-11-0286-001	331 E. Old York Road	4	inground	
40-11-0290-016	463 W. Old York Road	1, 6	inground	
40-11-0290-020	325 W. Old York Road	1	inground	
40-39-2211-001	230 Oxford Road	1, 4, 6	inground	
40-40-2654-029C	400 Oxford Road	1	inground	
40-15-0199-012 (B)	501 Oxford Road	1	inground	
40-11-0284-032	584 Park Drive	1, 6	inground	
40-11-0286-061	437 Park Drive	1,6	inground	
40-11-0284-034	580 Park Drive	1	inground	

TYPE OF MALFUNCTION:

- 1 HIGH WATER LEVEL IN TANK
- 2 WET AREAS NEAR SYSTEM OR SITE
- 3 NOTICEABLE ODORS
- 4 SEWER BACKUP INTO HOUSE
- 5 ABUNDANT GRASS GROWTH NEAR SYSTEM OR SITE
- 6 BACKFLUSH OF WATER FROM ABSORPTION AREA TO TANK
- 7 ANY OTHER INDICATION OF SYSTEM MALFUNCTION EXPLANATION

PIN	Street Address	Type of malfunction	Type of system	Investigated by SEO
40-25-0060-016	423 Petersburg Road	1	inground	
40-10-0636-067	498 Petersburg Road	1	inground	
40-11-0286-042	808 Petersburg Road	1	inground	
40-13-0126-017	1132 Petersburg Road	1	inground	
40-12-0344-066	1062 Petersburg Road	1	inground	
40-13-0126-019	1128 Petersburg Road	1	inground	
40-13-0126-021	1154 Petersburg Road	1,6	inground	
40-09-0531-018	378 Petersburg Road	1	ESM	
40-11-0286-031A	744 Petersburg Road	1	inground	
40-11-0286-030	748 Petersburg Road	1	inground	
40-12-0344-031	1115 Petersburg Road	1,4	inground	
40-12-0344-029	1131 Petersburg Road	1	inground	
40-11-0288-085	396 Pheasant Lane	1	ESM	
40-11-0288-082	390 Pheasant Lane	1	ESM	
40-11-0288-084	394 Pheasant Lane	1	ESM	
40-30-2644-003	232 Pine Road	1	inground	
40-39-2214-014	196 Pine School Road	1	inground	
40-12-0342-031A	211 Red Tank Road	4	inground	
40-12-0342-023	107 Red Tank Road	1	inground	
40-12-0342-011	31 Red Tank Road	1,6	inground	
40-12-0344-024	255 Red Tank Road	1	inground	
40-13-0126-014	261 Red Tank Road	1	inground	
40-12-0344-0191D	225 Red Tank Road	6	inground	
40-13-0126-032A	262 Red Tank Road	1,7-water infiltration, broken pipe	ESM	
40-10-0638-031	261 S. Ridge Road	1	inground	
40-11-0288-016C	1768 Rockledge Drive	1	ESM	
40-09-0529-028	1137 Rockledge Drive	1	inground	
40-11-0288-068	2 Sebastian Way	7-broken pipe in ESM	ESM	
40-10-0638-002	20 Shughart Road	7-tank has leak	inground	

TYPE OF MALFUNCTION:

- 1 HIGH WATER LEVEL IN TANK
- 2 WET AREAS NEAR SYSTEM OR SITE
- 3 NOTICEABLE ODORS
- 4 SEWER BACKUP INTO HOUSE
- 5 ABUNDANT GRASS GROWTH NEAR SYSTEM OR SITE
- 6 BACKFLUSH OF WATER FROM ABSORPTION AREA TO TANK
- 7 ANY OTHER INDICATION OF SYSTEM MALFUNCTION EXPLANATION

PIN	Street Address	Type of malfunction	Type of system	Investigated by SEO
40-10-0638-021M	155 Shughart Road	1,6	inground	
40-15-0201-015A	91 Smith Road	7-tank in poor condition	ESM	
40-24-0752-046	112 Spring Farm Circle	1	ESM	
40-10-0638-001	644 E. Springville Road	6	inground	
40-12-0344-017E	13 Tanger Road	7-jettted/cleaned drainfield	inground	
40-12-0344-094	284 Tanger Road	1	ESM	
40-12-0344-017I	5 Tanger Road	1, 6	inground	
40-12-0344-017H	7 Tanger Road	1, 6	inground	
40-13-0124-050	11 Timber Lane	1	inground	
40-08-0575-005	1745 W. Trindle Road	1	ESM	
40-40-2654-038	87 Victory Church Road	7-pump not working	ESM	
40-40-2656-015B	13 Victory Church Road	1, 6	inground	
40-40-2656-004A	59 Victory Church Road	1, 6	inground	
40-40-2654-030	92 Victory Church Road	7-pumping is for tank replacement	inground	
40-40-2656-019A	54 Victory Church Road	7-part of tank missing above water line	inground	
40-14-0140-070	359 Whiskey Springs Road	7-primary tank deterioration past rebar	ESM	
40-14-0140-015B	311 Whiskey Springs Road	1	inground	
40-10-0638-024	825 York Road	1	inground	
40-10-0638-045	839 York Road	7-repaired pump	ESM	
40-11-0286-033	598 Zion Road	1	inground	
40-31-2185-026	313 Zion Road	7-tank leaks,root infiltrating	inground	
40-32-2338-006	209 Zion Road	1	inground	
40-31-2185-017	328 Zion Road	1, 6	inground	
40-12-0342-057	225 Zion Road	1, 6	inground	